




S1030



EN User and maintenance manual DA Brugs- og vedligeholdelsesmanual
DE Bedienungs- und Wartungsanleitung ES Manual de uso y manutención
FI Käyttö- ja huolto-ohje FR Manuel d'utilisation et d'entretien
IT Manuale d'uso e manutenzione NL Gebruikers- en onderhoudshandleiding
NO Bruker- og vedlikeholdsveiledning PL Instrukcja obsługi i konserwacji
PT Manual de usuário e manutenção RO Manual de utilizare și întreținere
RU Руководство по эксплуатации SV Användar- och underhållshandbok
TR Kullanım ve bakım kılavuzu ZH 用户和维护手册



1. Introduction

1.1 About S1030 welding helmet

The S1030 product is personal protective equipment (PPE) for welders and fabrication personnel. It is designed for arc welding (MMA, MIG/MAG (GMAW), TIG (GTAW)) and plasma welding.

The S1030 welding helmet provides the users with protection for the eyes and face from harmful radiation. It includes an auto-darkening filter (ADF).

1.2 About this manual

Read this manual carefully before using the equipment for the first time. Pay particular attention to the safety instructions.

	Convention	Used For
	Note	Gives the user a piece of information of particular importance.
	Caution	Describes a situation that may result in damage to the equipment or system.
	Warning	Describes a potentially dangerous situation that may result in personal damage or fatal injury.

1.3 Disclaimer

While every effort has been made to ensure that the information contained in this guide is accurate and complete, no liability can be accepted for any errors or omissions. Kemppi reserves the right to change the specification of the product described at any time without prior notice. Do not copy, record, reproduce or transmit the contents of this guide without prior permission from Kemppi.

2. Safety

Warning:

- It is strictly forbidden to use any other than Kemppi branded parts or accessories with Kemppi's personal protection equipment. If you do not respect this safety regulation, serious damage for your health may occur.
- We recommend a usage period of 5 years. The period of use depends on various factors such as use, cleaning, storage and maintenance. Inspect the helmet before each use. Replace damaged or worn parts.
- Use all adjustment features for maximum protection.
- Never weld with the welding visor up or without the welding filter.
- If the auto-darkening filter (ADF) does not darken when the arc ignites, stop welding immediately. Inspect the ADF and its power supply. Change if necessary.

- Always use welding filters together with suitable protection plates.
- Never use a welding filter without the inner protection plate.
- Never use a scratched or damaged welding filter and ocular.
- Materials which may come into contact with the wearer's skin may cause allergic reactions to susceptible individuals.
- Only operate this product within the temperature range -5...+55 °C.
- The product is not intended for use in environments with a risk of explosion.
- The helmet does not protect against explosive devices or corrosive liquids.
- The helmet is not suitable for laser welding and oxy-acetylene welding/cutting processes.
- The helmet gives designed protection against high speed particles only at room temperature and only when all helmet components are properly attached, as described in the manual.
- When the helmet is worn over spectacles, they may transmit the impact of high speed particles, thus creating a hazard to the wearer.

 Caution: Make sure to remove any additional protection foil from both sides of the protection lens.

3. Adjusting headband

3.1 Headband top (see fig. 1W)

Adjust the headband to the correct depth on the head to ensure proper balance and stability.

3.2 Headband tightness (see fig. 1Y)

Adjust the tightness of the headband by turning the adjustment knob located on the back of the headband to the desired level.

3.3 Distance adjustment (see fig. 1Z)

To adjust the distance between the face and the lens, release the adjustment slot by pushing the locking button above the adjustment slot. Slide the helmet forwards or backwards to the desired position and tighten. Adjust both sides separately. Both sides must be in line for a correct view.

3.4 Angle adjustment (see fig. 1X)

The nine holes on the right side of the headband top allow for adjustment of the forward tilt of the helmet. To adjust, first, loosen the right outside tension adjustment knob. Next, lift the constraint arm tab and move it to the desired position. Finally, tighten the tension adjustment knob.

4. Helmet parts (see fig. 2)

1. Outer protection plate
2. Filter cartridge/ADF
3. Inner protection plate
4. Headband
5. Helmet shell
6. ADF holder
- A. Welding shade control/Grinding mode
- B. Sensitivity knob
- C. Delay time knob
- D. Lithium battery holder (CR2032)
- E. Low battery indicator

5. Auto-darkening filter functions

5.1 Selecting the operating mode

It is possible to select welding or grinding (see fig. 2E). “Grind” – Used for metal grinding applications. In this mode the shade function is turned off. The shade is fixed at the light state allowing a clear view for grinding with the helmet providing face protection.

The grind mode is intended for grinding, not for welding. Before resuming welding, the mode must be set to “Weld”.

“Weld” – Used for welding applications. In this mode, the shade function is turned on. When the auto-darkening filter senses the welding arc, it reacts according to the user-defined settings; shade level, delay time and sensitivity as required.

5.2 Selecting shade range and level

The S003 filter enables shade adjustment range from DIN 9-13. (See Fig. 2A)

Select the shade level you require according to the welding process you will use (see the chart on the back cover).



Note: The term “heavy metals” applies to steels, alloy steels, copper and its alloys, etc.

5.3 Selecting delay time

The delay time setting affects the time it takes to switch from dark to light state. It can be set at “MAX” (1.0 seconds) or “MIN” (0.1 seconds) by using the delay time knob (see fig. 2C).

“MAX” (1.0 seconds) – A longer delay is used in most welding applications, especially in high amperage (current) applications.

“MIN” (0.1 seconds) – A shorter delay is used in spot welding applications.

Longer delay can also be used for TIG (GTAW) welding in order to prevent the welding filter lens from lightening when the light path to the sensors is temporarily obstructed by a hand, torch, etc.

5.4 Selecting sensitivity

The sensitivity can be set to “HI” (High) or “LO” (Low) by using the sensitivity knob (see fig. 2B).

For best performance, it is recommended to set the sensitivity high at the beginning and then gradually reduce it until the filter reacts only to the flashes of the welding light, not to ambient lighting (direct sun, strong artificial light, the neighboring welder's arc, etc.).

“HI” (High) – For most welding applications, especially for low welding current work.

“LO” (Low) – Only in some specific surrounding lighting conditions in order to avoid unwanted triggering.

5.5 Power

The welding helmet is powered by solar energy and has a replaceable lithium battery. Replace battery when the “LOW BAT.” light is flashing.

6. Technical data

Filter model: S003

Standards: EN 175:1997, ISO 16321-2:2021

AS/NZS 1337.1, AS/NZS 1338.1

Filter dimension: 110 x 90 x 9 mm

View area: 96 x 39 mm

Optical classification: 1/1/1/2

True Color: Yes

Arc sensors: 2 pcs

Darkening degree: DIN 4/9-13

Sensitivity: Stepless

Delay time: 0.1 - 1.0 s

Reaction time: < 0.3 ms

UV/IR protection: DIN16

Power supply: Solar cell, lithium battery

Battery: 1 x CR2032

Low battery indicator: Yes

Grinding function: Yes

Operating temperature: -5°C – +55°C

7. Common problems and solutions

Irregular darkening/dimming

The headband has been set unevenly and there is an uneven distance from the eyes to the filter lens. (Re-adjust the headband to reduce the distance difference to the filter).

The filter does not darken or flickers

The outer cover plate is soiled or damaged (please change the cover lens);

Sensors are soiled / blocked or solar panel is blocked (Clean the surface of the sensor and make sure not to cover the sensors or the solar panel with your hand or other obstruction during welding);

Sensitivity is set to low or delay time is set to short (Adjust to the required level);

Make sure proper shade is selected (not grind mode).

The filter darkens even when the arc is not ignited

Sensitivity set too high (adjust sensitivity to the required level).

The filter remains dark after completing a weld
 Delay time set to too long (adjust delay time to the required level).

Slow response

Operating temperature is too low. Do not use at temperatures below -5°C.

Welding helmet slips

The headband is not properly adjusted. (Readjust the headband.)

8. Storage and maintenance

When not in use, the filter should be stored in a dry place within the temperature range of -10°C – +60°C. Prolonged exposure at temperatures above 45°C may decrease the battery lifetime of the filter. It is recommended to keep the solar cells of the filter in the dark or not exposed to light during storage in order to maintain the powerdown mode. This can be achieved by simply placing the filter face down on the storage shelf. Both inner and outer protection plates (polycarbonate), must be used in conjunction with the auto-darkening filter in order to protect it against permanent damage.

It is always necessary to keep the solar cells and the light sensors of the filter free of dust and spatters: cleaning can be done with a soft tissue or a cloth soaked in mild detergent.

Never use aggressive solvents such as acetone.

If protection plates are in any way damaged, they must be immediately replaced.

Replacing outer cover plate:

Remove the filter holder by moving the locks toward center and lift up the filter holder to remove/replace the outer protection plate.

Replacing inner cover plate:

Place your fingernail into the recess below the cartridge of the view window and flex the lens upwards until it releases from the edges of the cartridge of the view window.

Markings

Helmet	
KMP	Manufacturer
EN 175	Standard reference and conformity marking
F	Class
CE	CE marking (European conformity)
16321 KMP W13 C 1-M CE	
16321	Standard reference
KMP	Manufacturer
W	Welding protector
13	Maximum filter shade
C	Impact level
1-M	Average medium head size
CE	CE marking (European conformity)
Filter	
KMP	Manufacturer
4	Light shade
9-13	Dark shade DIN 9-13
1	Optical class
1	Diffusion of light class
1	Variations in luminous transmittance class
2	Angle dependency class
379 CE	
Standard reference and conformity marking	

Welding process	A (Current)																					
	1.5	6	10	15	30	40	60	70	100	125	150	175	200	225	250	300	350	400	450	500	600	
Covered electrodes					8				9	10			11		12		13		14			
MAG					8				9	10			11		12		13		14			
TIG					8				9	10			11		12		13		14			
MIG with heavy metals									9				10			11		12		13		
MIG with light alloys										10				11		12		13		14		
Air-arc gouging													10		11		12		13		15	
Plasma jet cutting													9		10		11		12		13	
Microplasma arc welding	4	5	6	7	8	9				10			11		12							

DA	FI	NL	PT	SV
Nedblandningsniveau	Tummuusaste	Verduisteringsniveau	Nível de sombreamento	Täthetsgrad
Svejseproces	Hitsausprosessi	Lasproces	Processo de soldagem	Svetsmetod
A (Strøm)	A (Virta)	A (Stroom)	A (corrente)	A (ström)
Beklædte elektroder	Päälystetyt elektrodit	Bedekte elektroden	Elektrodas cobertos	MMA
MAG, TIG,	MAG, TIG,	MAG, TIG,	MAG, TIG,	MAG, TIG,
MIG (tungmetaller)	MIG (raskasmalit)	MIG (zware metalen)	MIG (metais pesados)	MIG (tunga applikationer)
MIG (lette legeringer)	MIG (kevyet seokset)	MIG (lichte legeringen)	MIG (ligas leves)	MIG (lättmetall)
Luft-buemejsling	Hiiikaaritaltaus	Gutsen met luchtboog	Goivagem com arco de ar	Bågluftsmejsling
Plasma-stråleskæring	Plasmaelikkaus	Plasmasnijden	Corte a jato de plasma	Plasmaskærning
Mikroplasmabuesvejsning	Mikroplasmakaarihartsaus	Microplasma booglassen	Soldagem a arco com microplasma	Mikroplasmasvetsning
DE	FR	NO	RO	TR
Schutzstufe	Niveau de densité	Nyansenivå	Nivel de umbră	Ton seviyesi
Schweißprozess	Procédé de soudage	Sveiseprosess	Proces de sudare	Kaynak işlemeli
A (Strom)	A (courant)	A (strøm)	A (Curent)	A (Akım)
Umhüllte Elektroden	Électrodes couvertes	Dekkede elektroder	Electrozi acoperiți	Örtülü elektrotlar
MAG, WIG,	MAG, TIG,	MAG, TIG,	MAG, TIG,	MAG, TIG,
MIG (Schwermetalle)	MIG (métaux lourds)	MIG (tunge metaller)	MIG (metale grele)	MIG (ağır metaller)
MIG (Leichtmetalle)	MIG (alliages légers)	MIG (lette legeringer)	MIG (aliaje ușoare)	MIG (hafif alaşımlar)
Fugenhobeln mit Luft-Lichtbogen	Gougeage à l'arc pneumatique	Kullbuemeisling	Crăitiuire cu electrod cu aer	Hava ark oluk açma
Plasmaschneiden	Découpe plasma	Plasmajetskjæring	Tâiere cu jet de plasmă	Plazma jet kesme
Mikroplasma-Lichtbogenschweißen	Soudage à l'arc microplasma	Mikroplasmalymsbuesveisning	Sudare cu arc de microplasmă	Mikroplazma ark kaynağı
ES	IT	PL	RU	ZH
Nivel de Oscurecimiento	Livello di oscuramento	Stopień zaciemnienia	Уровень затемнения	遮光度
Proceso de soldadura	Procedimento di saldatura	Proces spaw.	Сварочный процесс	焊接工艺
A (Corriente)	A (corrente)	A (prąd)	Сварочный процесс	A (电流)
Electrodos recubiertos	Elettrodi coperti	Elektrody otulone	А (tok)	覆盖的电极
MAG, TIG,	MAG, TIG,	MAG, TIG,	Покрытые электроды	MAG, TIG
MIG (metales pesados)	MIG (metalli pesanti)	MIG (metale ciężkie)	MAG, TIG,	MIG (重金属)
MIG (aleaciones ligeras)	MIG (leghe leggere)	MIG (stopy lekkie)	Сварка MIG (тяжелые металлы)	MIG (轻合金)
Corte por arco de aire	Scricatura ad arco d'aria	Žłobienie łykiem powietrznym	Сварка MIG (легкие сплавы)	空气电弧气刨
Corte con plasma	Taglio con plasma	Cięcie plazmowe	Воздушно-дуговая строжка	等离子喷射切割
Soldadura por arco de microplasma	Saldatura ad arco con microplasma	Spawanie łykowwe mikroplazmą	Плазменная резка	微等离子弧焊



userdoc.kemppi.com



EN Declarations of Conformity DA Overensstemmelseserklæringer
 DE Konformitätserklärungen ES Declaraciones de conformidad
 FI Vaatimustenmukaisuusvakuutuksia FR Déclarations de conformité
 IT Dichiarazioni di conformità NL Verklaringen van overeenstemming
 NO Samsvarserklæringer PL Deklaracje zgodności PT Declarações de conformidade RO Declarație de conformitate RU Заявления о соответствии SV Försäkran om överensstämmelse TR Uygunluk Beyanı ZH 符合性声明

